



3725 Nicholson Road
P.O. Box 0505
Franksville, WI
53126 - 0505

drives & systems

Development - Manufacturing - Integration - Service

Phone: (262) 8865678

Fax: (262) 5045396

<http://www.unicous.com>

Email: unicous@unicous.com



Warning: Failure to follow these instructions could lead to catastrophic damage of the drive.

The blue jumper is **only** for drives that do not have a thermal switch that connects to the DSP. If the base part number of your drive does not appear below, then dispose of the blue jumper and connect the thermal switch to the DSP. Contact the factory if you are uncertain.

The following base part numbers need the blue jumper:

318794, 318795, 319953, 319958, 321157, 321158, 321159, 321160, 321161, 321166, 321167, 321168, 321169, 321170, 321171, 321172, 321173, 321174, 321179, 321180, 321181, 321182, 321233, 321234, 321858, 321859, 321886, 321887, 321888, 321889, 321890, 321891, 321892, 321893, 321899, 321900, 321901, 321902, 321903, 321904, 321905, 321906, 321907, 321982, 321983, 322033, 322034, 322047, 322363, 322364, 322365, 322366, 322784, 322788, 322851, 322904, 322905, 322906, 322907, 322908, 322909, 322910, 322911, 322919, 322920, 322921, 322922, 322923, 322924, 322925, 322926, 322927, 322928, 322990, 322991, 322992, 322993, 323084, 323085, 323829, 323877, 323895, 323896, 323897, 323898, 323899, 323900, 323901, 323902, 323910, 323911, 323912, 323913, 323914, 324414, 324415, 324416, 324417, 324512, 324514, 324620, 324867, 324924, 324925, 324926, 324927, 324928, 324929, 324930, 324931, 324932, 324933, 324934, 324935, 324936, 324937, 325371, 325372, 325373, 325374, 325375, 325376, 325377, 325378, 325379, 325407, 325816, 326876, 326877, 326878, 326879, 327977, 328009, 328010, 328206, 328338, 328391, 328540, 328541, 328542, 328543, 328544, 328545, 328546, 328547, 328892, 328894, 328975, 328976, 329436.



Figure 1: DSP with Jumper Installed



Figure 2: DSP with Thermal Switch Installed